

Construction:

Start Level:

Start Time:

End Level:

End Time:

Level Change:

Test Results:

Test Failure:

## **Maryland Catchment Basin and Containment Sump Test Report**

MDE Facility I.	D. #: <b>1656</b>							
Facility Name: Easton Point 24 Hr Station				UST Owner: Tim Miller				
Facility Address: 930 Port St.				Owner Address: 28102 Baileys Neck Rd.				
City: Easton	State: MD	Zip: 216	501	City: Easton	Stat	te: MD Z	ip: 21601	
				Owner Telephone Number: (410) 310-3553				
Testing Company: Clean Fuels Associates								
Company Telephone Number: (410) 757-7576								
Test Date: 06/26/19		Weather Condition: S		unny	Tem	Temperature: 85 F		
<u> </u>								
Product:	Regular Gasoh	ol Nor		n-Ethanol 91		ULS Diesel		
Testing:	√ Check One	√ Ch		eck One		√ Check One		
	☐ Spill Buck	Spill Bucket		Spill Bucket		Spill Bucket		
	Stage I Bucket		Stage I Bucket			Stage I Bucket		
	Dispenser Sump			☐ Dispenser Sump		☐ Dispenser Sump		
	Dispenser			aptiliti Sump				

☐ STP Sump

☐ Tank Top Sump

☐ Transition Sump

☐ Vent Riser Sump

☐ Other (Describe):

☐ Double-walled (vacuum

performed in accordance

with manufacturer or PEI/

8 3/8"

10:30 am

8 3/8"

11:30 am

0"

☐ Fail

Time:

☐ Single-walled

test method must be

☐ STP Sump

☐ Tank Top Sump

☐ Transition Sump

☐ Vent Riser Sump

☐ Other (Describe):

Double-walled (vacuum

performed in accordance

with manufacturer or PEI/

7"

10:32 am

11:32 am

0"

☐ Fail

☐ Single-walled

RP1200)

☐ Pass

test method must be

- Hydrostatic and vacuum test failures must be reported to MDE immediately and within 2 hours of the test.

☐ Pass

RP1200)

- A liquid level drop of 1/8 inch or greater in 1 hour is considered a test failure.

STP Sump

☐ Single-walled

RP1200)

Pass

test method must be

Tank Top Sump

Transition Sump

Vent Riser Sump Other (Describe):

☐ Double-walled (vacuum

performed in accordance

with manufacturer or PEI/

7 1/8"

10:30 am

7 1/8"

11:30 am

0"

☐ Fail

Reported to MDE Date:

Product:	Off-Road Diesel	Premium Gasohol					
Testing:	√ Check One	√ Check One	√Check One				
	Spill Bucket	Spill Bucket	☐ Spill Bucket				
	Stage I Bucket	Stage I Bucket	☐ Stage I Bucket				
	Dispenser Sump	☐ Dispenser Sump	Dispenser Sump				
	#	<u>#</u>	<u>#</u>				
	STP Sump	STP Sump	STP Sump				
	Tank Top Sump	Tank Top Sump	Tank Top Sump				
	Transition Sump	Transition Sump	Transition Sump				
	☐ Vent Riser Sump	☐ Vent Riser Sump	☐ Vent Riser Sump				
	U Other (Describe):	Other (Describe):	Other (Describe):				
			TG: 1 11 1				
Construction:	☐ Single-walled	☐ Single-walled	☐ Single-walled				
	☐ Double-walled (vacuum	Double-walled (vacuum	☐ Double-walled (vacuum				
	test method must be	test method must be	test method must be				
	performed in accordance	performed in accordance	performed in accordance				
	with manufacturer or PEI/	with manufacturer or PEI/	with manufacturer or PEI/				
Ct and I amount	RP1200)	RP1200) 7 1/8"	RP1200)				
Start Level:	7 1/4"						
Start Time: End Level:	10:35 am	10:35 am					
End Time:	7 1/4" 11:35 am	7 1/8"					
	0"	11:35 am 0"					
Level Change: Test Result:	☐ Pass ☐ Fail		☐ Pass ☐ Fail				
Test Result. Test Failure	Reported to MDE Date	l	☐ Fass ☐ Faii				
	<u> </u>	**************************************					
- Hydrostatic and vacuum test failures must be reported to MDE immediately and within 2 hours of							
the test.			••				
- A liquid level drop of 1/8 inch or greater in 1 hour is considered a test failure.							
Tester Certification (check one):							
☐ MDE Technician MDIC T							
MDE Inspector MDIC I							
Precision Tester: Test Method Hydrostatic Certification Expiration Date:							
Tester's Name (print) : Matthew Eader Tester's Signature:							
Comments:							
All buckets clean and dry. Filled all spills and then started measuring them from the bottom to the water level. ALL PASS.							

Copy of the test report must be maintained by the owner/operator for a period of 5 years and made available to the Department upon request and during UST inspections.

Page 2 of 2